

D2NU2J

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	31237 KM
File nr. :	1450920	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PVP685 / WV2ZZZ2KZHX034905 /		yr of constructionr :	/
E-File nr. :		First registration :	29/09/2016
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	
Object nr. :	ONBEKEND	Fuel :	
Classification :	DELIVERY VAN A	Environment Class:	EURO 6
Customer company :	ONBEKEND	Co2:	122g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	102	kW:	75
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

Interior

[x] DASHBORD HOLE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

[x] FRONT THRESHOLD/RIGHT/CENTER

DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 10 LU =48.00 EUR	232.88 EUR		50 %	280.88 EUR

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE MISSING/INCOMPLETE

	Repair paint - LI	New paint - E	Depr.	Total
6 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	43.74 EUR

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	MIRROR COVER	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
43.74	110.64	329.40	280.88	22.50	114.00	0	0	0	0
43.74	110.64	164.70	140.44	11.25	57.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
154.38	746.78	0	901.16
HOG: 0	BG: 3		NA Deprec. 527.77
			0.00%
			TOTAL 527.77

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/11/2017 Hour : 12:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	