

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	139670 KM
File nr. :	1456397	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HZC488 / WVWZZZ3CZEE067606 /		yr of constructionr :	/
E-File nr. :		First registration :	04/11/2014
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	48269	Fuel :	
Classification :	C	Environment Class:	EURO 5
Customer company :	MEULEMAN NV	Co2:	116g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	NOK	[x]	4-6/	Rim :	[x] WHEEL SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	50 LU =240.00 EUR	0 EUR	403.51 EUR	50 %	643.51 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	30 LU =144.00 EUR	0 EUR	435.72 EUR	50 %	579.72 EUR

Interior

[x]	BOOT LID IN	CARVED			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED		
		Repair paint - LI	New paint - E	Depr.	Total
8	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	SIDE PROTECTION		BROKEN / CRACKED		
		Repair paint - LI	New paint - E	Depr.	Total
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	45.88 EUR

TYRE FRONT RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
7	5 LU =24.00 EUR			50 %	24.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR
		Description	Unit price	Depr.	Total
2	1	FENDER REAR LEFT	588.00 EUR	50 %	588.00 EUR
		Description	Unit price	Depr.	Total
5	1	DOOR REAR RIGHT	367.20 EUR	50 %	367.20 EUR
		Description	Unit price	Depr.	Total
6	1	CHROOM BAGET ACHTERBUMMPER	90.00 EUR	50 %	90.00 EUR
		Description	Unit price	Depr.	Total
7	1	TYRE	108.00 EUR	50 %	108.00 EUR
		Description	Unit price	Depr.	Total
8	1	SIDE INDICATOR	20.40 EUR	50 %	20.40 EUR

1	2	3	4	5	6	7	8	9	10
159.88	1231.51	211.80	63.00	946.92	114.00	227.00	44.40	0	0
102.88	615.76	105.90	63.00	473.46	57.00	161.00	22.20	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
203.88	2794.63	0	2998.51
HOG: 0	BG: 0		NA Deprec. 1601.20
			0.00%
			TOTAL 1601.20

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/11/2017 Hour : 08:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	