

D5HC61

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	179087 KM
File nr. :	1453112	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JEE663 / WV2ZZZ2KZFX056135 /		yr of constructionr :	/
E-File nr. :		First registration :	24/11/2014
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	136g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	102	kW:	75
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		[x]
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :		[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap : [x] MISSING/INCOMPLETE
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT MUDGUARD/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE +DEUK

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR

[x] WINDSCREEN/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	0 EUR		50 %	
5 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x] FRONT MUDGUARD/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	0 EUR		50 %	
2 25 LU =120.00 EUR	0 EUR	177.91 EUR	50 %	297.91 EUR

[x] BONNET/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	0 EUR		50 %	
2 15 LU =72.00 EUR	0 EUR	307.10 EUR	50 %	379.10 EUR

[x] LIGHTS/RIGHT/FRONT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	0 EUR		50 %	
2 20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

[x] FRONT BUMPER/RIGHT

DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	0 EUR		50 %	
2 20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	68.82 EUR

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	LIGHT UNIT	225.00 EUR	50 %	225.00 EUR
2	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
2	1	BONNET	401.40 EUR	50 %	401.40 EUR
2	1	FENDER FR	129.60 EUR	50 %	129.60 EUR
4	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
5	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR

1	2	3	4	5	6	7	8	9	10
68.82	1927.41	110.64	22.50	395.40	0	0	0	0	0
68.82	963.70	110.64	11.25	197.70	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
179.46	2345.31	0	2524.77
HOG: 0	BG: 3		NA Deprec. 1352.12
			0.00%
			TOTAL 1352.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/10/2017 Hour : 15:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	