

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	80526 KM
<b>File nr. :</b>	1456382	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1AHQ161 / VF3XS9HUCAZ060500 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	12/01/2011
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	PEUGEOT / EXPERT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	72417	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 4
<b>Customer company :</b>	CEGELEC BUILDING SERVICES	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	90	<b>kW:</b>	66
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	65	R	15	
Rear tyre	215	65	R	15	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Interior

[x] STEERING WHEEL OTHER DAMAGES

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

Number	Code	Description	Unit price	Depr.	Total
[x]		REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE		
4	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]		REAR DOOR/RIGHT/RIGHT	OTHER DAMAGES		BINNENIN PLAAT
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]		FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE		+DEUK
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR
[x]		FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE		+DEUK
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR
		Repair paint - LI	New paint - E	Depr.	Total
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

### Interior

Number	Code	Description	Unit price	Depr.	Total
[x]		BOOT IN R	OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

## Others

### CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	68.82 EUR
Number	Code	Description	Unit price	Depr.	Total
1	I 4	bestelwagen-laadruimte-a-vab-rein-06	CLEANING INTERIOR	23.41 EUR	93.64 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	PANEEL	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	PANEEL	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
162.46	434.62	54.00	110.64	74.00	0	0	0	0	0
162.46	272.63	27.00	110.64	37.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
383.74	451.98	0	<b>835.72</b>
HOG: 0	BG: 3		NA Deprec. 609.73
			0.00%
			<b>TOTAL 609.73</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 14/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	