

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	14136 KM
File nr. :	1459733	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LBG756 / WDD1760121V090222 /		yr of constructionr :	/
E-File nr. :		First registration :	10/08/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	45735	Fuel :	
Classification :	N	Environment Class:	EURO 6
Customer company :	KPMG ADVISORY	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	[x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	BROKEN / CRACKED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

Accessories and others

- [x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/RIGHT/REAR			SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E		Depr.		Total
4	0 LU =0.00 EUR		318.35 EUR			50 %		318.35 EUR
[x]	FRONT BUMPER/RIGHT/SIDE			SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E		Depr.		Total
2	0 LU =0.00 EUR		211.80 EUR			50 %		211.80 EUR
[x]	ROOF/CENTER/LEFT			DENT				
	Number	Code	Description		Unit price	Depr.		Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT		63.00 EUR			63.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR			50 %	

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	211.80	63.00	318.35	120.00	0	0	0	0	0
29.16	105.90	63.00	159.18	60.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
92.16	650.15	0	742.31
HOG: 0	BG: 0		NA Deprec. 417.24
			0.00%
			TOTAL 417.24

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/11/2017 Hour : 08:56 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	