APPRAISAL

DD3QFQ

[X] EFFECTIVE   [ ] NOT EXECUTED   [X] COLLECTION   [ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	**Cleanliness :**	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		**Mileage :**	107589 KM
File nr. :	1459183	**Mileage start / arrival:**	0 / 0
Reg number / Chassis / Ref :		**Mileag ref. service :**	0
1DDI371 / TMBJJ93T3C9061581 /		**yr of constructionr :**	/
E-File nr. :		**First registration :**	16/04/2012
VFS-nr. :		**Color :**	BEIGE
Make + Model :	SKODA / SUPERB COMBI	**Fuel type :**	DIESEL
Object nr. :	12055	**Fuel :**	
Classification :		**Environment Class:**	EURO 5
Customer company :	ERICSSON N.V./S.A.	**Co2:**	114g/km
Driver :		**Remote controls:**	2
Covering :	LEATHER	**Number keys :**	2 [x]
Vehicle kind :	VEHICLE	**Seats (minivan) :**	0
Vehicle type :	SUPERB COMBI GreenLine Eleganc.DPF 105PK	**Country registration :**	BELGIUM

VAT over the margin - car:	No	**Metallic paint:**	Yes
Variant car:	BREAK	**Engine size:**	1598
Gear box :	Manueel	**Number of places:**	5
Number of gears:	6	**Number of doors:**	5
HP:	105	**kW:**	77
Fisc HP		**Imported vehicle:**	
Animals transported:	No	**Smoked in vehicle:**	No
Due date vehicle inspection:		**Extra set of tires:**	No
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :		OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

APPRAISAL

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]   REAR BUMPER/LEFT/LEFT   SCRATCH WITH PAINT DAMAGE

[x]   REAR MUDGUARD/RIGHT/CENTER   SCRATCH WITH PAINT DAMAGE

Interior

[x]   SEAT FL   OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Others

RIM FRONT LEFT

Number	Code		Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code		Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code		Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code		Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
380.00	0	0	0	0	0	0	0	0	0
380.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
380.00	**0**	**0**	**380.00**
HOG: 0	BG: 0		NA Deprec. 380.00
			0.00%
			TOTAL **380.00**

APPRAISAL

[x] = Status Modification

Pictures :   No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	

NOT EXECUTED :	No
Reason :	
Remark :	

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 16/11/2017 **Hour :** 09:01	
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	