



BMW 5: 1EDW374

| | | | |
|-------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WBAFW91090DW47904 | Versionname: | 5 BER 520d |
| First Registrationdate: | 1/11/2012 | Fiscalpower: | Eff.Dyn.Ed.St/Stp 163PK |
| Expertise Mileage: | 67815 | Power Kw: | 120 |
| Bodytype: | Berline | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3807 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunction | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 225/55/17/97 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 3 mm | Fr.R. | Pirelli: 3 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment


| | |
|---------|------------|
| Runflat | Yes |
|---------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1036,04 |
|-------------------|----------------|


| | |
|--|--------------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



| | |
|-------------------------------------|---------------|
| Alloy rim F L, Damaged, E - Replace | 277,44 |
|-------------------------------------|---------------|



| | |
|-----------------------------------|---------------|
| Door panel F L, Tear, E - Replace | 132,00 |
|-----------------------------------|---------------|



| | |
|---|--------|
| Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|--------|



| | |
|-------------------------------------|--------|
| Alloy rim F R, Damaged, E - Replace | 277,44 |
|-------------------------------------|--------|



| | |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Ashtray, Not functioning (well), P - Check | 0,00 |
|--|------|

