


BMW 116 D: 1EGL227

Vinnumber:	WBA1C910X0J505016	Versionname:	Eff.Dyn.Ed. 116PK
First Registrationdate:	26/11/2012	Fiscalpower:	
Expertise Mileage:	161400	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Body color:	met.
Transmission:	Back	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OK	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3704
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	882,47
Rearview mirror housing L, Scratch(es), Acceptable	0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Wing R R, Scratch(es), It - Spot repair 115,56



Front bumper, Scratch(es), It - Spot repair 115,56



Door R R, Bump(s), LI - Repair and paint (complete) 366,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Repaired, P - Check 0,00

