


AUDI A3: 1DPY095

Vinnnumber:	WAUZZZ8P9DA016309	Versionname:	A3 SB Attraction St./St.
First Registrationdate:	18/07/2012	Fiscalpower:	105PK
Expertise Mileage:	65658	Power Kw:	77
Bodytype:	Hatchback	Body color:	Anthracite
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1633
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes
------------	------------












Total cost ex VAT	2220,26
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

	Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
	Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	Wing R R, Scratch(es), LI - Repair and paint (complete)	356,20
	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
	Rearview mirror housing R, Broken, LI - Repair and paint (complete)	115,56
	Wing F R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		

