


BMW 5: 1HHU309

Vinnnumber:	WBA5N21000D497221	Versionname:	5 GRAN TURISMO 520dA (EU5) 163PK Aut.
First Registrationdate:	28/07/2014	Fiscalpower:	
Expertise Mileage:	201559	Power Kw:	120
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2603
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	245/50/18/100 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

 Runflat **Yes**

Total cost ex VAT	1133,22
Wing R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), It - Spot repair	115,56


 Rearview mirror L complete, Scratch(es), Acceptable **0,00**
No pictures to display

 Windscreen, Stone chip(s), E - Replace **560,64**



Door R R, Repaired, Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 362,02

