


BMW 3: 1FT0016

Vinnumber:	WBA3K11050F827045	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	21/10/2013	Fiscalpower:	
Expertise Mileage:	194944	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	-600KM	Parking lot:	2606
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 1,8 mm	Re.R.	Michelin: 1,8 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		0,00
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Backrest cover F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		

