


BMW 3: 1GFD807

Vinnnumber:	WBA3D11070J625749	Versionname:	3 BER 318d 136PK
First Registrationdate:	22/01/2014	Fiscalpower:	
Expertise Mileage:	116687	Power Kw:	100
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2401
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear


	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

	Compressor	Yes
Total cost ex VAT		1904,66
Bonnet, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Seat cover F L, Dirty, Cleaning 12,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18

