



AUDI A4: 1GCY709

Vinnumber:	WAUZZZ8K9EA071106	Versionname:	A4 BER TDie 136PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	178971	Power Kw:	100
Bodytype:	Berline	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2510
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	CD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS base
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1166,94
-------------------	---------

Rocker panel inner R R, Bump(s), LI - Repair and paint (complete)	115,56
---	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Interior, Dirty, Cleaning 72,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Interior, Smell, Ozone treatment 152,58

No pictures to display

Roof, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s), Acceptable 0,00

No pictures to display