



<b>AUDI Q3: 1EAY083</b>			
Vinnumber:	<b>WAUZZZ8U8DR035604</b>	Versionname:	<b>Q3 136PK</b>
First Registrationdate:	<b>8/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>133434</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>6600 KM OF 360 DAGEN</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Seats electric F L	
GPS storage	<b>SD</b>	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>215/65/16/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

<b>Assistance equipment</b>			
Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			
	<b>327,36</b>		
Wing F R, Repaired, P - Check			
	<b>0,00</b>		



Door R L, Repaired, P - Check	<b>0,00</b>
-------------------------------	-------------



Door F L, Repaired, P - Check 0,00



Tailgate, Scratch(es), It - Spot repair 115,56



Front bumper, Difference in color, LI - Repair and paint (complete) 211,80



Brand badge R, Worn, P - Check 0,00



Door R R, Repaired, P - Check 0,00



Door F R, Repaired, P - Check 0,00



Bumper corner R R, Scratch(es), Acceptable 0,00



Door R R, Bump(s), Acceptable 0,00



Parking sensor R, Strained , P - Check 0,00



Wing moulding F L, Deformed, P - Check 0,00

