



<b>AUDI A3: 1GAA353</b>			
Vinnnumber:	<b>WAUZZZ8V2EA099209</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>3/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>71421</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3322</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 3 mm</b>	Re.R.	<b>Dunlop: 3 mm</b>





<b>Assistance equipment</b>	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>	<b>622,88</b>
<b>Bonnet, Chemical polution, LI - Repair and paint (complete)</b>	<b>290,08</b>



<b>Bumper R, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Seat cover F R, Stain, Forfeit</b>	<b>12,00</b>



<b>Luggage space cover, Incomplete, E - Replace</b>	<b>10,00</b>
---	--------------

			Seat cover F L, Stain, Forfeit	12,00	
			Front bumper, Bump(s), LI - Repair and paint (complete)	235,80	
			Door R L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>					
Wing R L, Scratch(es), Acceptable					0,00
<i>No pictures to display</i>					
Roof, Bump(s), PDR - Knock out without painting					63,00
