



AUDI A5: 1EEA706			
Vinnumber:	<b>WAUZZZ8T1DA033165</b>	Versionname:	<b>A5 SB TDie DPF 136PK</b>
First Registrationdate:	<b>5/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>151478</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1524</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear			
Summer tyres:	<b>245/45/17/95 V LightMetal</b>		
	Fr.L.	Fr.R.	Uniroyal: 4 mm
	Re.L.	Re.R.	Uniroyal: 4 mm

Assistance equipment			
Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	2524,84
Bumper grille, Damaged, E - Replace	84,00



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
Door F L, Scratch(es), LI - Repair and paint (complete)	382,02




Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Tear, Le - Replace and paint	862,80
--	--------

