


AUDI A4: 1FXW333

Vinnumber:	WAUZZZ8K1EN020255	Versionname:	A4 BER TDi 120PK
First Registrationdate:	2/12/2013	Fiscalpower:	
Expertise Mileage:	104956	Power Kw:	88
Bodytype:	Berline	Body color:	Anthracite
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3810
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	DVD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/16/95 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	575,24
-------------------	---------------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tailgate, Chemical polution, LI - Repair and paint (complete)	301,68
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 63,00



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display