



FORD Galaxy: 1DNW121			
Vinnnumber:	WF0MXXGBWMCK24583	Versionname:	GALAXY Econetic Trend St&St DPF 115PK
First Registrationdate:	3/07/2012	Fiscalpower:	
Expertise Mileage:	149584	Power Kw:	85
Bodytype:	Minibus	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	Yes	Parking lot:	511
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options			
Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	SD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	NOT OK
Idle position	NOT OK	Clutch test	NOT OK
Engine startingtime	NOT OK	Wiper fluid level	OK
Exhaust gass	NOT OK	Lighting	OK
Transmission	NOT OK	Wiperblades	OK
Handbrake	NOT OK		

Degree of wear				
	225/350/317/398 W LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2194,22
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Certificate Of Conformity, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Registration Document, Missing, E - Replace 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

