



FORD C-MAX: 1AVN196

Vinnumber:	WFOJXXWPBJBC70007	Versionname:	C-MAX Trend DPF 95PK
First Registrationdate:	1/04/2011	Fiscalpower:	
Expertise Mileage:	177381	Power Kw:	70
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3707
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 0 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2350,03
-------------------	---------

Internal Boot Lining L, Damaged, E - Replace	69,00
--	-------



Tailgate, Rust, LI - Repair and paint (complete)	301,68
--	--------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Luggage space cover, Missing, E - Replace 50,00



Interior, Dirty, Forfeit 36,00



Door R R, Difference in color, Acceptable 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover R R, Scratch(es), E - Replace 30,00



Protection plate M, Tear, E - Replace 62,00



Rear window, Scratch(es), E - Replace 370,00



Ceiling, Damaged, E - Replace 494,00





Internal Boot Lining R, Damaged, E - Replace 69,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00

