


FORD S Max: 1EOT771

Vinnnumber:	WF0SXXGBW5CY73441	Versionname:	S-MAX Econetic Trend
First Registrationdate:	8/02/2013	Fiscalpower:	St&St DPF 115PK
Expertise Mileage:	141262	Power Kw:	85
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2402
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes
------------	------------

Total cost ex VAT	190,00
Front bumper, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00

