


FORD Mondeo: 1EYR148

Vinnumber:	WF0GXXGBBGDU08508	Versionname:	CLIP Econetic Titanium
First Registrationdate:	23/04/2013	Fiscalpower:	115PK
Expertise Mileage:	133642	Power Kw:	85
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	LAATSTE SERVICE OP 10 KM		
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

 Total cost ex VAT 1130,95

 Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

 Bonnet, Bump(s), Acceptable 0,00

No pictures to display

 Boot carpet, Stain, Cleaning 50,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Stain, 67 - Polish 55,19



Covering interior front pillar R, Stain, Acceptable 0,00

No pictures to display

Ceiling, Stain, Cleaning 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Stain, 67 - Polish 55,19



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Stain, 67 - Polish 55,19



Door F R, Stain, 67 - Polish 55,19



Maintenance, Maintenance, P - Check 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), 67 - Polish 55,19

