



**FORD Focus: 1EE0327**

Vinnnumber:	<b>WF0LXXGCBLCY79161</b>	Versionname:	<b>FOCUS CLIP. EConetic T.Trend Sport 95PK</b>
First Registrationdate:	<b>8/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>139018</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

**Assistance equipment**

Compressor	<b>Yes</b>
------------	------------

Total cost ex VAT	<b>782,73</b>
-------------------	---------------

Floor covering F L, Burned, Smart repair	<b>64,32</b>
--	--------------



Floor covering F L, Hole, Smart repair	<b>64,32</b>
--	--------------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F R, Scratch(es), It - Spot repair 115,56



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Bump(s), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*