



**BMW X1: 1PVZ489**

Vinnumber:	<b>WBAHT710005E73871</b>	Versionname:	
First Registrationdate:	<b>3/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>89235</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3231</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Seats electric F L
GPS storage	<b>HD</b>	Sun Roof electric
Windows electric F		Panoramic roof
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

<b>225/45/19/92 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 2 mm</b>	Fr.R.	<b>Bridgestone: 2 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

**Assistance equipment**

Runflat **Yes**

Total cost ex VAT **395,64**

Alloy rim F R, Damaged, LI - Repair and paint (complete) **95,00**



Alloy rim R L polished, Damaged, LI - Repair and paint (complete) **95,00**

No pictures to display

Alloy rim R R polished, Damaged, LI - Repair and paint (complete) **95,00**



Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Maintenance book, Missing, E - Replace	0,00
--	------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

