



## CITROEN C4 Picasso: 1DXC802

Vinnumber:	<b>VF7UA9HR8CJ695877</b>	Versionname:	<b>GR.C4 PICASSO</b>
First Registrationdate:	<b>24/09/2012</b>		<b>7pl.Excl.BMP FAP 112PK</b>
Expertise Mileage:	<b>60894</b>	Fiscalpower:	<b>Aut</b>
Bodytype:		Power Kw:	<b>82</b>
Gearbox:	<b>Automatic</b>	Body color	<b>Brown</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>38647 KM</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2813</b>
Maintenance	<b>17-10-2015</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

## Options

GPS storage		Central consol F
GPS storage	<b>HD</b>	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>215/55/16/93 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 266,99

Door R R, Scratch(es), Acceptable 0,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00



Wing R L, Scratch(es), 67 - Polish 55,19



Roof pillar R, Bump(s), Acceptable 0,00



Bonnet, Hail damage, PDR - Hail 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Hail damage, PDR - Hail 0,00



Door F R, Scratch(es), Acceptable 0,00



Roof pillar L, Hail damage, PDR - Hail 0,00



Internal Boot Lining R, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

