



MERCEDES A: 1KPX733

Vinnnumber:	WDD1760121V069117	Versionname:	1.5 A 180 CDI
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	56004	Power Kw:	80
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3210
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/95 V Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	744,30
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------




Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Seat cover F R, Stain, Cleaning	12,50
---------------------------------	-------

