



MERCEDES C 220: 1FRG486

Vinnumber:	WDD2040021A903808	Versionname:	CDI AVANTGARDE
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	42661	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1308
Maintenance:	B5 DEPASSE DEPUIS 35 JOURS		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT **1217,66**

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) **95,00**



Door R L, Scratch(es), 67 - Polish **55,19**



Seat cover F L, Stain, Acceptable

0,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)

259,80



Alloy rim F R, Scratch(es), Acceptable

0,00



Grill, No damage, P - Check

0,00



Door F L, Scratch(es), 67 - Polish

55,19



Mirror side blinker L, Scratch(es), Acceptable

0,00



Seat cover F R, Stain, Acceptable

0,00



Maintenance, Maintenance, Execute

0,00



Tailgate, Bump(s), LI - Repair and paint (complete)

349,68



Door R R, Bump(s), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 307,80

