



MERCEDES C 220 CDI: 1FPE131

Vinnnumber:	WDD2040021A905272	Versionname:	C BER 220CDI BE Edition Elegance 163PK
First Registrationdate:	12/09/2013	Fiscalpower:	
Expertise Mileage:	47893	Power Kw:	120
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	HD	Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	660,00
-------------------	--------

Door R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Bump(s), LI - Repair and paint (complete)	307,80
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper moulding R R, Broken, E - Replace	14,40



Door R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wing R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80

