



MINI Mini: 1FWY777

Vinnumber:	WMWSW31030T756702	Versionname:	MINI Cooper D 112PK DPF
First Registrationdate:	22/11/2013	Fiscalpower:	
Expertise Mileage:	69520	Power Kw:	82
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2824
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	175/65/15/84 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

	Jack	Yes
Total cost ex VAT		2196,41
Luggage space cover, Broken, E - Replace		60,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35





Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s), LI - Repair and paint (complete) 380,20



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F R, Scratch(es), E - Replace 74,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Bump(s), LI - Repair and paint (complete) 268,18



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper spoiler F, Scratch(es), E - Replace 84,00



Wing trim R R, Scratch(es), E - Replace 84,00



Roof, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 314,08



Windscreen, Repaired, Acceptable 0,00

