



NISSAN QASHQAI: 1GQX990

Vinnumber:	SJNFAAJ11U1069358	Versionname:	
First Registrationdate:	1/05/2024	Fiscalpower:	
Expertise Mileage:	62007	Power Kw:	
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4813
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting:	Headlighting Xenon		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/19/96 W LightMetal			
Summer tyres:	Fr.L.	Continental: 1,5 mm	Fr.R.	Continental: 1,5 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes
------------	------------

Total cost ex VAT	3549,68
-------------------	---------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tyre R L, Damaged, E - Replace 132,00



Wing trim R L, Missing, E - Replace 84,00



Door R L, Bump(s) and scratch(es), Le - Replace and paint 946,92



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 370,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Seat cover F L, Damaged, E - Replace 360,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Smell, Ozone treatment 152,58

No pictures to display

Interior, Dirty, Chemical cleaning 144,00



Luggage space cover, Incomplete, E - Replace 240,00

