



FORD S Max: 1BON006			
Vinnumber:	WF0SXXGBWSBY41317	Versionname:	S-MAX Econetic Trend St&St DPF 115PK
First Registrationdate:	18/07/2011	Fiscalpower:	
Expertise Mileage:	173868	Power Kw:	85
Bodytype:	MPV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3726
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Other: 4 mm	Re.R.	Other: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1732,62
Outer door handle F R, Scratch(es), Paint			75,00



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	372,60
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Side window trim F R, Damaged, E - Replace 99,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display

Wheel cover R L, Missing, E - Replace 36,00



Interior, Dirty, Cleaning 72,00



Front bumper, Strained , I - Repair 72,00

