


**MERCEDES B: 1EHZ705**

Vinnumber:	<b>WDD2462001J131224</b>	Versionname:	<b>B 180 CDI BE 109PK</b>
First Registrationdate:	<b>10/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>50982</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>- 8 DAGEN</b>	Parking lot:	<b>1124</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Sun Roof electric
GPS storage	<b>HD</b>	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/45/17/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 3 mm</b>	Fr.R.	<b>Fulda: 3 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>0,00</b>
-------------------	-------------

Windscreen, Scratch(es), Acceptable	<b>0,00</b>
-------------------------------------	-------------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Maintenance, Maintenance, Execute	<b>0,00</b>
-----------------------------------	-------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper corner R L, Unclassped, N - Fit/Remove	0,00
---	------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Crack, E - Replace	0,00
--------------------------------	------

