


**RENAULT SCENIC: 1FDU718**

Vinnnumber:	<b>VF1JZNA648961697</b>	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	<b>157123</b>	Power Kw:	<b>1</b>
Bodytype:	<b>Minibus</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>	Parking lot:	<b>503</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	Luggage cover
GPS storage	
GPS storage	<b>SD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS base</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>No</b>
Tires wear profile	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Idle position	<b>NOT OK</b>	Clutch test	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Wiper fluid level	<b>NOT OK</b>
Exhaust gass	<b>NOT OK</b>	Lighting	<b>NOT OK</b>
Transmission	<b>NOT OK</b>	Wiperblades	<b>NOT OK</b>
Handbrake	<b>NOT OK</b>		

**Degree of wear**

	<b>205/55/17/95 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	211,80
Certificate Of Conformity, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Registration Document, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	0,00
<i>No pictures to display</i>	
Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Instruction book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80

