



OPEL Vivaro 2900: 1EHS771

Vinnumber:	W0LJ7B7BBDV601505	Versionname:	VIVARO 2900 COMBI L2H1 HD.(E5)115PK Aut.
First Registrationdate:	6/12/2012	Fiscalpower:	
Expertise Mileage:	28664	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	9		
Number head rests:	9		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

- Radio CD
- Windows electric F
- Type of headlighting **Headlighting Halogen**
- Type of Lining **Lining fabrics**

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/65/16/107 T Steel			
Winter tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Total cost ex VAT	0,00
Seat cover F L, Tear, Repair/replace (lump sum)	64,32



Step L, Scratch(es), Acceptable 0,00



Trunk door R R, Bump(s), PDR - Knock out without painting 63,00



Bumper corner R R, Scratch(es), F - Replace 75,00

Bumper corner R R, Scratch(es), E - Replace 75,00



Bumper corner R L, Scratch(es), Acceptable 0,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 279,15



Trunk door R L, Bump(s) and scratch(es), It - Spot repair 115,56



Wing R R, Bump(s), Acceptable 0,00



Spare wheel, Missing, E - Replace 0,00



Ignition key, Broken, E - Replace 0,00



Bumper R, Damaged, E - Replace 329,40

