



OPEL ASTRA BREAK: MZ8277

Vinnumber:	WOLBE8EL4G8107235	Versionname:	
First Registrationdate:	17/11/2016	Fiscalpower:	
Expertise Mileage:	14837	Power Kw:	81
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1509
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/17/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment


Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	631,08
-------------------	--------

Wing R L, Bump(s), PDR - Knock out without painting	111,00
---	--------



Door R R, Bump(s), PDR - Knock out without painting	63,00
---	-------




Seat cover F L, Stain, Cleaning

24,00



Bonnet, Bump(s), LI - Repair and paint (complete)

338,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

