



**RENAULT Megane: 1EHG260**

Vinnumber:	<b>VF1KZ140648153613</b>	Versionname:	<b>MEGANE GT Energy TomTom Ed.110PK</b>
First Registrationdate:	<b>3/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>196400</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 1240,95

Door panel F L, Stain, P - Check 0,00



Wing R L, Bad repair, P - Check 0,00





Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), PDR - Knock out without painting 142,20



Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Repaired, P - Check 0,00



Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Roof pillar L, Repaired, P - Check 0,00



Seat F L compl, Worn, P - Check 0,00



Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Scratch(es), Smart repair 110,64



Internal Boot Lining R, Scratch(es), Smart repair 110,64



Luggage space cover, Damaged, Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper cover R M, Damaged, E - Replace 150,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 366,35



Door frame R L, Scratch(es), Acceptable 0,00

No pictures to display

Glove compartment lid, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Cleaning 25,00







Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------

