



| | | | |
|------------------------------------|--------------------------|--------------|---|
| MINI Countryman: 1FVI599 | | | |
| Vinnumber: | WMWZD31000WP93435 | Versionname: | MINI COUNTRYMAN Cooper D DPF 112PK |
| First Registrationdate: | 6/11/2013 | Fiscalpower: | |
| Expertise Mileage: | 59408 | Power Kw: | 82 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3709 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|--------------------------------|------------------------------|----------------------|--|
| Options | | | |
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS portable | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| | 205/60/16/92 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

| | | | |
|---|------------|------------|----------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1321,55 |
| Roof, Bump(s) and scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door R L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door panel R R, Damaged, E - Replace | | | 114,00 |





Door trim R R, Scratch(es), E - Replace 114,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bad repair, Acceptable 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 390,35



Foglight R, Broken, E - Replace 138,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bodywork, Not original part, Sticker removal 0,00



Bonnet, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper spoiler F, Scratch(es), E - Replace 87,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 75,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display