



RENAULT Megane: 1GVL225			
Vinnumber:	<b>VF1KZ140650741246</b>	Versionname:	<b>MEGANE GT Energy Business 110PK</b>
First Registrationdate:	<b>12/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>172495</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1408</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/55/16/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Kleber: 7 mm</b>	Re.R.	<b>Kleber: 7 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>1142,52</b>
Interior, Stain, Cleaning			<b>72,00</b>



Bonnet, Stone chip(s), Acceptable		<b>0,00</b>
-----------------------------------	--	-------------

Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Armrest F Mid, Burned, Smart repair	64,32



Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Door panel R R, Scratch(es), E - Replace	114,00
--	--------



Luggage space cover, Deformed, E - Replace	240,00
--	--------



Door panel F R, Scratch(es), E - Replace	114,00
--	--------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Door R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), E - Replace	415,20

