



VOLKSWAGEN Golf: 1GAU470

Vinnnumber:	VWVZZZAUZEW180178	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	10/12/2013	Fiscalpower:	
Expertise Mileage:	64766	Power Kw:	77
Bodytype:	Hatchback	Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1409
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		


Degree of wear

	205/55/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	697,85
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Repaired, Acceptable	0,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Seat cover F R, Damaged, Smart repair	64,32
---------------------------------------	-------



Door F L, Repaired, Acceptable	0,00
--------------------------------	------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door R L, Repaired, Acceptable	0,00
--------------------------------	------

