



VOLKSWAGEN TOURAN: 1DOZ373

Vinnumber:	WVGZZZ1TZBW010901	Versionname:	
First Registrationdate:	8/11/2010	Fiscalpower:	
Expertise Mileage:	270583	Power Kw:	77
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1610
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Windows electric R	
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 V Steel			
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes
------------	------------

Total cost ex VAT	1816,71
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Rearview mirror housing R, Crack, LI - Repair and paint (complete) 115,56



Wheel cover F R, Scratch(es), E - Replace 30,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Wheel cover F L, Scratch(es), Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50

