



VOLVO V40: 1FJN795

Vinnnumber:	YV1MV8481E2085172	Versionname:	V40 D2 Base 115PK
First Registrationdate:	17/07/2013	Fiscalpower:	
Expertise Mileage:	87431	Power Kw:	84
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	17-2-2017	Parking lot:	3332
Maintenance:	OK		
Maintenance:	69987 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	120,00
-------------------	--------

Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Wing R R, Bad repair, P - Check	0,00
---------------------------------	------




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00



Bumper R, Repaired, P - Check 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Windscreen, Repaired, P - Check 0,00



Door F L, Repaired, P - Check 0,00

