



VOLVO V60: 1GAL906			
Vinnnumber:	YV1FW8481E1184268	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	6/12/2013	Fiscalpower:	
Expertise Mileage:	188401	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	235/40/18/95 MS LightMetal			
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	0,00
Bumper F R, Scratch(es), It - Spot repair	115,56



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Windscreen, Stone chip(s), Windscreen repair 0,00



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Tear, E - Replace 62,00



Protection plate M, Tear, E - Replace 62,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

