



MERCEDES A: 1FSL628			
Vinnumber:	WDD1760121J190413	Versionname:	A 180CDI BE Edition 109PK
First Registrationdate:	10/10/2013	Fiscalpower:	
Expertise Mileage:	119523	Power Kw:	80
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2523
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	195/65/15/91 T Steel			
	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment	
Compressor	Yes

Total cost ex VAT	382,00
Wheel cover F R, Scratch(es), E - Replace	30,00



Wheel cover R L, Scratch(es), E - Replace	30,00
---	--------------



Interior, Dirty, Cleaning	12,00
---------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Full screen GPS, Missing, E - Replace	250,00
---------------------------------------	--------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display