



VOLKSWAGEN Golf: 1HXE362

Vinnnumber:	WVWZZZAUZFP554953	Versionname:	GOLF VAR Trendline 90PK
First Registrationdate:	20/10/2014	Fiscalpower:	
Expertise Mileage:	151374	Power Kw:	66
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2129
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT

	866,56
--	---------------

Wing R L, Bump(s), PDR - Knock out without painting

	63,00
--	--------------



Tailgate, Bump(s), LI - Repair and paint (complete)

	301,68
--	---------------





Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Bumper R, Bad repair, Acceptable	0,00
----------------------------------	------

