



VOLVO XC60: 1FKW804			
Vinnnumber:	YV1DZ31A1E2523186	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	1/08/2013	Fiscalpower:	
Expertise Mileage:	155694	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4808
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		


Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Panoramic roof
Steering wheel multifunctional	Central consol F
Type of headlighting	Headlighting Halogen
Type of Lining	Lining leather
Type of climate control	Autom climate control
	Front parking sensors
	Rear parking sensors

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	235/60/18/103 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		288,00	
Alloy rim F R polished, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Door R L, Repaired, Acceptable		0,00	
<i>No pictures to display</i>			
Bonnet, Bad repair, Acceptable		0,00	



Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Radio, Not functioning (well), P - Check	0,00
<i>No pictures to display</i>	
Luggage space cover, Missing, E - Replace	288,00
	
Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	