


**SKODA Superb: 1FRR618**

Vinnnumber:	<b>TMBJJ73T9E9022503</b>	Versionname:	<b>SUPERB COMBI GreenLine Elegance 105PK</b>
First Registrationdate:	<b>3/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>160895</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1208</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated	
Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting:	<b>Headlighting Xenon</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>
------------	------------

Total cost ex VAT	1068,16
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

