


RENAULT Grand Scenic: 1EIN908

Vinnumber:	VF1JZ14A648361523	Versionname:	GR.SCENIC Energ.Dynamique 5pl.FAP
First Registrationdate:	14/12/2012	Fiscalpower:	110PK
Expertise Mileage:	171798	Power Kw:	81
Bodytype:	Hatchback	Body color:	Burgundy
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3705
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric	
GPS storage	Panoramic roof	
GPS storage	SD Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	Tow bar removable
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	0,00
-------------------	------

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
-------------------------------------------------------------------	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Roof, Hail damage, PDR - Hail 0,00



Backrest cover F L, Damaged, Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display