



VOLVO XC60: 1DUF387

Vinnumber:	YV1DZ31A1D2385149	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	29/08/2012	Fiscalpower:	
Expertise Mileage:	154628	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2108
Number of doors:	5		
Number of seats:	2		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT 382,02

Door panel F L, Crack, Acceptable 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display


Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Door R L, Bump(s), L - Repair and paint (complete) 382,02



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display