



OPEL Vivaro 2700: 1DPH371

Vinnnumber:	WOLJ7A7ABCV632345	Versionname:	VIVARO 2700 COMBI L1H1 DPF(E5)115PK Aut.
First Registrationdate:	12/07/2012	Fiscalpower:	
Expertise Mileage:	33407	Power Kw:	84
Bodytype:	MPV	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2304
Number of doors:	5		
Number of seats:	9		
Number head rests:	9		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	NOT OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/65/16/104 T Steel			
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment


Spare wheel	Yes
-------------	------------

Total cost ex VAT	1007,56
Trunk door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	182,00




Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	361,13
---	--------





Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Bumper R, Scratch(es), Smart repair 110,64



Floor covering R, Damaged, Acceptable 0,00



Interior, Dirty, Cleaning 12,00



Front bumper, Scratch(es), Smart repair 110,64



Bodywork, Not original part, Acceptable 0,00

No pictures to display