



PEUGEOT 508: 1FRR616

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber: | VF38D9HD8DL048702 | Versionname: | 508 BER e-HDi Active STT |
| First Registrationdate: | 3/10/2013 | Fiscalpower: | 115PK |
| Expertise Mileage: | 152395 | Power Kw: | 84 |
| Bodytype: | Berline | Body color: | Beige |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1607 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Seats electric F L |
| GPS storage | Central consol F |
| GPS storage | HD Front parking sensors |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/60/16/99 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|---|--------|
| Total cost ex VAT | 614,60 |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |



| | |
|---|--------|
| Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) | 307,80 |
|---|--------|



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

