


OPEL Astra: 1EZQ799

Vinnumber:	WOLPE8EX7D8050002	Versionname:	ASTRA BRE ecoFLEX Cosmo St/St 130PK
First Registrationdate:	30/04/2013	Fiscalpower:	
Expertise Mileage:	123189	Power Kw:	96
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4721
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/16/1691 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes
------------	------------

Total cost ex VAT	2809,48
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80












Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	366,35
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	GPS, Scratch(es), Acceptable	0,00
	Bumper grille, Damaged, E - Replace	32,40
	Tailgate, Bump(s), LI - Repair and paint (complete)	301,68
	Rearlight L, Scratch(es), E - Replace	114,00
	Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
	Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
